

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : **STA** **0+000**

KONDISI PERKERASAN : **Sedang**

LEBAR PERKERASAN : **4** **M**

TYPE PERKERASAN : **Aspal**

LOKASI : **STA** **0+100**

KONDISI PERKERASAN : **Baik**

LEBAR PERKERASAN : **3,5** **M**

TYPE PERKERASAN : **Aspal**

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh	DPUPR KAB.BANJARNEGARA	FIRDAUS & DAMAS	1

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : **STA** **0+200**

KONDISI PERKERASAN : **Baik**

LEBAR PERKERASAN : **3,5** **M**

TYPE PERKERASAN : **Aspal**

LOKASI : **STA** **0+300**

KONDISI PERKERASAN : **Baik**

LEBAR PERKERASAN : **3,5** **M**

TYPE PERKERASAN : **Aspal**

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh	DPUPR KAB.BANJARNEGARA	FIRDAUS & DAMAS	2

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



30/09/2025 08:30:36
7°24'43"S 109°37'57"E
Kabupaten Banjarnegara
#Ruas I.45 Masaran - Kutawuluh
#STA 0+400
#Survei Jalan #DPUPR Kab Banjarnegara



30/09/2025 08:31:32
7°24'44"S 109°37'54"E
Kabupaten Banjarnegara
#Ruas I.45 Masaran - Kutawuluh
#STA 0+500
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA** **0+400**

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN :

LOKASI : **STA** **0+500**

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	3

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



30/09/2025 08:32:22
7°24'45"S 109°37'51"E
Kabupaten Banjarnegara
#Ruas I.45 Masaran - Kutawuluh
#STA 0+600
#Survei Jalan #DPUPR Kab Banjarnegara



30/09/2025 08:33:11
7°24'45"S 109°37'47"E
Kabupaten Banjarnegara
#Ruas I.45 Masaran - Kutawuluh
#STA 0+700
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA** **0+600**

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN :

LOKASI : **STA** **0+700**

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	4

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : **STA 0+800**

KONDISI PERKERASAN :
 LEBAR PERKERASAN : M
 TYPE PERKERASAN :

LOKASI : **STA 0+900**

KONDISI PERKERASAN :
 LEBAR PERKERASAN : M
 TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



30/09/2025 08:36:00
7°24'42"S 109°37'39"E
Kabupaten Banjarnegara
#Ruas 1.45 Masaran - Kutawuluh
#STA 1+000
#Survei Jalan #DPUPR Kab Banjarnegara



30/09/2025 08:36:54
7°24'44"S 109°37'36"E
Kabupaten Banjarnegara
#Ruas 1.45 Masaran - Kutawuluh
#STA 1+100
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA** **1+000**

LOKASI : **STA** **1+100**

KONDISI PERKERASAN :

Baik

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

KONDISI PERKERASAN :

Baik

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	6

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



30/09/2025 08:37:44
7°24'45"S 109°37'34"E
Kabupaten Banjarnegara
#Ruas 1.45 Masaran - Kutawuluh
#STA 1+200
#Survei Jalan #DPUPR Kab Banjarnegara



30/09/2025 08:38:42
7°24'47"S 109°37'31"E
Kabupaten Banjarnegara
#Ruas 1.45 Masaran - Kutawuluh
#STA 1+300
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA** **1+200**

LOKASI : **STA** **1+300**

KONDISI PERKERASAN :

Baik

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

KONDISI PERKERASAN :

Baik

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	7

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



30/09/2025 08:39:42
7°24'50"S 109°37'28"E
Kabupaten Banjarnegara
#Ruas 1.45 Masaran - Kutawuluh
#STA 1+400
#Survei Jalan #DPUPR Kab Banjarnegara



30/09/2025 08:40:51
7°24'51"S 109°37'25"E
Kabupaten Banjarnegara
#Ruas 1.45 Masaran - Kutawuluh
#STA 1+500
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 1+400**

LOKASI : **STA 1+500**

KONDISI PERKERASAN :

Sedang

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

KONDISI PERKERASAN :

Rusak Berat

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	8

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



30/09/2025 08:41:44
7°24'51"S 109°37'23"E
Kabupaten Banjarnegara
#Ruas 1.45 Masaran - Kutawuluh
#STA 1+600
#Survei Jalan #DPUPR Kab Banjarnegara



30/09/2025 08:43:02
7°24'50"S 109°37'20"E
Kabupaten Banjarnegara
#Ruas 1.45 Masaran - Kutawuluh
#STA 1+700
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 1+600**

LOKASI : **STA 1+700**

KONDISI PERKERASAN :

Rusak Ringan

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

KONDISI PERKERASAN :

Sedang

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	9

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : **STA** **1+800**

LOKASI : **STA** **1+810**

KONDISI PERKERASAN : **Rusak Berat**
 LEBAR PERKERASAN : **3,5** **M**
 TYPE PERKERASAN : **Aspal**

KONDISI PERKERASAN : **Rusak Ringan**
 LEBAR PERKERASAN : **3,5** **M**
 TYPE PERKERASAN : **Aspal**

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	10

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : **STA** **1+900**

LOKASI : **STA** **2+000**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : **3,5** **M**
 TYPE PERKERASAN : **Aspal**

KONDISI PERKERASAN : **Sedang**
 LEBAR PERKERASAN : **3,5** **M**
 TYPE PERKERASAN : **Aspal**

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	11

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : **STA** **2+050**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3,5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA** **2+100**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3,5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	12

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : **STA** **2+200**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3,5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA** **2+300**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 3,5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	13

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : **STA 2+400**

LOKASI : **STA 2+500**

KONDISI PERKERASAN :

Baik

 LEBAR PERKERASAN :

3,5

 M
 TYPE PERKERASAN :

Aspal

KONDISI PERKERASAN :

Baik

 LEBAR PERKERASAN :

3,5

 M
 TYPE PERKERASAN :

Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : **STA 2+600**

LOKASI : **STA 2+700**

KONDISI PERKERASAN :

Baik

 LEBAR PERKERASAN :

3,5

 M
 TYPE PERKERASAN :

Aspal

KONDISI PERKERASAN :

Baik

 LEBAR PERKERASAN :

3,5

 M
 TYPE PERKERASAN :

Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : **STA 2+800**

LOKASI : **STA 2+900**

KONDISI PERKERASAN :

Baik

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

KONDISI PERKERASAN :

Baik

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	16

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : **STA 3+000**

LOKASI : **STA 3+100**

KONDISI PERKERASAN :

Baik

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

KONDISI PERKERASAN :

Baik

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	17

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : **STA 3+200**

LOKASI : **STA 3+300**

KONDISI PERKERASAN :

Baik

 LEBAR PERKERASAN :

3,5

 M
 TYPE PERKERASAN :

Aspal

KONDISI PERKERASAN :

Baik

 LEBAR PERKERASAN :

3,5

 M
 TYPE PERKERASAN :

Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	18

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : **STA 3+400**

LOKASI : **STA 3+500**

KONDISI PERKERASAN :

Baik

 LEBAR PERKERASAN :

3,5

 M
 TYPE PERKERASAN :

Aspal

KONDISI PERKERASAN :

Baik

 LEBAR PERKERASAN :

3,5

 M
 TYPE PERKERASAN :

Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	19

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



30/09/2025 09:02:27
7°25'16"S 109°36'32"E
Kabupaten Banjarnegara
#Ruas I.45 Masaran - Kutawuluh
#STA 3+600
#Survei Jalan #DPUPR Kab Banjarnegara



30/09/2025 09:03:22
7°25'17"S 109°36'29"E
Kabupaten Banjarnegara
#Ruas I.45 Masaran - Kutawuluh
#STA 3+700
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 3+600**

LOKASI : **STA 3+700**

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN :

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh	DPUPR KAB.BANJARNEGARA	FIRDAUS & DAMAS	20

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



30/09/2025 09:04:19
7°25'18"S 109°36'25"E
Kabupaten Banjarnegara
#Ruas I.45 Masaran - Kutawuluh
#STA 3+800
#Survei Jalan #DPUPR Kab Banjarnegara



30/09/2025 09:04:39
7°25'18"S 109°36'25"E
Kabupaten Banjarnegara
#Ruas I.45 Masaran - Kutawuluh
#STA 3+810
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 3+800**

LOKASI : **STA 3+810**

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN :

KONDISI PERKERASAN :
LEBAR PERKERASAN : M
TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh	DPUPR KAB.BANJARNEGARA	FIRDAUS & DAMAS	21

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



30/09/2025 09:05:41
7°25'18"S 109°36'22"E
Kabupaten Banjarnegara
#Ruas 1.45 Masaran - Kutawuluh
#STA 3+900
#Survei Jalan #DPUPR Kab Banjarnegara



30/09/2025 09:06:34
7°25'19"S 109°36'19"E
Kabupaten Banjarnegara
#Ruas 1.45 Masaran - Kutawuluh
#STA 4+000
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 3+900**

LOKASI : **STA 4+000**

KONDISI PERKERASAN :

Baik

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

KONDISI PERKERASAN :

Baik

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

NO. RUAS 45	NAMA RUAS Masaran - Kutawuluh	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 22
----------------	----------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



30/09/2025 09:07:40
7°25'22"S 109°36'17"E
Kabupaten Banjarnegara
#Ruas 1.45 Masaran - Kutawuluh
#STA 4+100
#Survei Jalan #DPUPR Kab Banjarnegara



30/09/2025 09:08:22
7°25'24"S 109°36'15"E
Kabupaten Banjarnegara
#Ruas 1.45 Masaran - Kutawuluh
#STA 4+200
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 4+100**

LOKASI : **STA 4+200**

KONDISI PERKERASAN :

Baik

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

KONDISI PERKERASAN :

Baik

LEBAR PERKERASAN :

3,5

 M
TYPE PERKERASAN :

Aspal

NO. RUAS 45	NAMA RUAS Masaran - Kutawuluh	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 23
----------------	----------------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



30/09/2025 09:09:19
 7°25'26"S 109°36'12"E
 Kabupaten Banjarnegara
 #Ruas 1.45 Masaran - Kutawuluh
 #STA 4+300
 #Survei Jalan #DPUPR Kab Banjarnegara



30/09/2025 09:10:13
 7°25'27"S 109°36'9"E
 Kabupaten Banjarnegara
 #Ruas 1.45 Masaran - Kutawuluh
 #STA 4+400
 #Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 4+300**

LOKASI : **STA 4+400**

KONDISI PERKERASAN :
 LEBAR PERKERASAN : M
 TYPE PERKERASAN :

KONDISI PERKERASAN :
 LEBAR PERKERASAN : M
 TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh	DPUPR KAB.BANJARNEGARA	FIRDAUS & DAMAS	24

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



30/09/2025 09:11:05
 7°25'29"S 109°36'6"E
 Kabupaten Banjarnegara
 #Ruas 1.45 Masaran - Kutawuluh
 #STA 4+500
 #Survei Jalan #DPUPR Kab Banjarnegara



30/09/2025 09:12:02
 7°25'31"S 109°36'3"E
 Kabupaten Banjarnegara
 #Ruas 1.45 Masaran - Kutawuluh
 #STA 4+600
 #Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 4+500**

LOKASI : **STA 4+600**

KONDISI PERKERASAN :
 LEBAR PERKERASAN : M
 TYPE PERKERASAN :

KONDISI PERKERASAN :
 LEBAR PERKERASAN : M
 TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh	DPUPR KAB.BANJARNEGARA	FIRDAUS & DAMAS	25

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : STA 4+610

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

LOKASI : STA 4+700

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	26

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : STA 4+800

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

LOKASI : STA 4+900

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	27

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : **STA** **4+950**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3,5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA** **5+000**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3,5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	28

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Masaran - Kutawuluh



LOKASI : **STA** **5+100**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 3,5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA** **5+186**

KONDISI PERKERASAN : Rusak Berat

LEBAR PERKERASAN : 3,5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
45	Masaran - Kutawuluh		FIRDAUS & DAMAS	29