


**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 5,5 M  
TYPE PERKERASAN : Aspal


LOKASI : **STA 0+100**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	1

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	2

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI :           **STA**           **0+400**

LOKASI :           **STA**           **0+500**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    4,5            M  
TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    4,5            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 3
---------------------	----------------------------------	------------------------	-----------------------------------	--------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI :           **STA**           **0+600**

LOKASI :           **STA**           **0+700**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    4,5            M  
TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    4,5            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 4
---------------------	----------------------------------	------------------------	-----------------------------------	--------------

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI :           **STA           0+800**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    4,5            M  
TYPE PERKERASAN             :    Aspal

LOKASI :           **STA           0+900**

KONDISI PERKERASAN           :    Sedang  
LEBAR PERKERASAN            :    4,5            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	5

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI :           **STA           1+000**

LOKASI :           **STA           1+100**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       4,5            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       4,5            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	6

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI :           **STA           1+200**

LOKASI :           **STA           1+300**

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       4,5            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       4,5            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	7

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI : **STA 1+400**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+500**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	8

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI : **STA 1+600**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal



LOKASI : **STA 1+700**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	9

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI : **STA 1+800**

LOKASI : **STA 1+900**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	10

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI : **STA 2+000**

LOKASI : **STA 2+100**

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	11

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



14 Okt 2025 09.07.51  
7°22'6"S 109°40'11"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 2+200  
#Survei Jalan #DPUPR Kab Banjarnegara



14 Okt 2025 09.08.49  
7°22'7"S 109°40'9"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 2+300  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 2+200**

LOKASI : **STA 2+300**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	12

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



14 Okt 2025 09.09.57  
7°22'8"S 109°40'6"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 2+400  
#Survei Jalan #DPUPR Kab Banjarnegara



14 Okt 2025 09.10.57  
7°22'8"S 109°40'3"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 2+500  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 2+400**

LOKASI : **STA 2+500**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	13

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



14 Okt 2025 09.12.11  
7°22'8"S 109°39'59"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 2+600  
#Survei Jalan #DPUPR Kab Banjarnegara



14 Okt 2025 09.13.14  
7°22'8"S 109°39'56"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 2+700  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 2+600**

LOKASI : **STA 2+700**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	14

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



14 Okt 2025 09.14.08  
7°22'8"S 109°39'54"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 2+800  
#Survei Jalan #DPUPR Kab Banjarnegara



14 Okt 2025 09.15.09  
7°22'8"S 109°39'50"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 2+900  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 2+800**

LOKASI : **STA 2+900**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	15

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



14 Okt 2025 09.16.19  
7°22'7"S 109°39'45"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 3+000  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 3+000**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal



14 Okt 2025 09.17.14  
7°22'6"S 109°39'43"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 3+100  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 3+100**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	16

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



14 Okt 2025 09.18.24  
7°22'5"S 109°39'40"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 3+200  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 3+200**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal



14 Okt 2025 09.19.36  
7°22'5"S 109°39'37"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 3+300  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 3+300**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	17

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI :           **STA           3+400**

LOKASI :           **STA           3+500**

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN            :     4,5            M  
TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN            :     4,5            M  
TYPE PERKERASAN             :     Aspal

NO. RUAS III. 17	NAMA RUAS Banjarnangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 18
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI :           **STA           3+600**

LOKASI :           **STA           3+700**

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN            :     4,5            M  
TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN            :     4,5            M  
TYPE PERKERASAN             :     Aspal

NO. RUAS III. 17	NAMA RUAS Banjarnangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 19
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI : **STA 3+800**

LOKASI : **STA 3+900**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	20

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI : **STA 4+000**

LOKASI : **STA 4+100**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	21

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



14 Okt 2025 09:29:16  
7°22'4"S 109°39'9"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 4+200  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 4+200**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal



14 Okt 2025 09:30:24  
7°22'3"S 109°39'6"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 4+300  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 4+300**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 22
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



14 Okt 2025 09:31:33  
7°22'3"S 109°39'2"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 4+400  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 4+400**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal



14 Okt 2025 09:32:35  
7°22'2"S 109°38'59"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarmangu - Rakit  
#STA 4+500  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 4+500**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 23
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA            4+600**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    4,5            M

TYPE PERKERASAN             :    Aspal

LOKASI :           **STA            4+700**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    4,5            M

TYPE PERKERASAN             :    Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 24
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA            4+800**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    4,5            M

TYPE PERKERASAN             :    Aspal

LOKASI :           **STA            4+900**

KONDISI PERKERASAN           :    Sedang

LEBAR PERKERASAN            :    4,5            M

TYPE PERKERASAN             :    Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 25
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI : STA 5+000

LOKASI : STA 5+100

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarnangu - Rakit		Firdaus & Damas	26

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit



LOKASI : STA 5+200

LOKASI : STA 5+300


KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarnangu - Rakit		Firdaus & Damas	27

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit



LOKASI : STA 5+400

LOKASI : STA 5+500

KONDISI PERKERASAN : Sedang  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	28

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI : STA 5+600

LOKASI : STA 5+700

KONDISI PERKERASAN : Sedang  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	29

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit





LOKASI :               **STA               5+800**

KONDISI PERKERASAN               :               Sedang

LEBAR PERKERASAN               :               4,5               M

TYPE PERKERASAN               :               Aspal

LOKASI :               **STA               5+900**

KONDISI PERKERASAN               :               Sedang

LEBAR PERKERASAN               :               4,5               M

TYPE PERKERASAN               :               Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 30
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :               **STA               6+000**

KONDISI PERKERASAN               :               Sedang

LEBAR PERKERASAN               :               4,5               M

TYPE PERKERASAN               :               Aspal

LOKASI :               **STA               6+100**

KONDISI PERKERASAN               :               Sedang

LEBAR PERKERASAN               :               4,5               M

TYPE PERKERASAN               :               Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 31
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**





14 Okt 2025 10.11.12  
 7°21'57"S 109°38'8"E  
 Kabupaten Banjarnegara  
 #Ruas III. 17 Banjarnegu - Rakit  
 #STA 6+200  
 #Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : STA 6+200

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Aspal



14 Okt 2025 10.13.20  
 7°21'58"S 109°38'5"E  
 Kabupaten Banjarnegara  
 #Ruas III. 17 Banjarnegu - Rakit  
 #STA 6+300  
 #Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : STA 6+300

KONDISI PERKERASAN : Sedang  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Aspal

NO. RUAS III. 17	NAMA RUAS Banjarnegu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 32
---------------------	---------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarnegu - Rakit**



14 Okt 2025 10.14.24  
 7°21'59"S 109°38'1"E  
 Kabupaten Banjarnegara  
 #Ruas III. 17 Banjarnegu - Rakit  
 #STA 6+400  
 #Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : STA 6+400

KONDISI PERKERASAN : Sedang  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Aspal



14 Okt 2025 10.15.29  
 7°21'59"S 109°37'59"E  
 Kabupaten Banjarnegara  
 #Ruas III. 17 Banjarnegu - Rakit  
 #STA 6+500  
 #Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : STA 6+500

KONDISI PERKERASAN : Sedang  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Aspal

NO. RUAS III. 17	NAMA RUAS Banjarnegu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 33
---------------------	---------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarnegu - Rakit**





LOKASI : **STA 6+600**

LOKASI : **STA 6+700**

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS III. 17	NAMA RUAS Banjarnangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 34
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit



LOKASI : **STA 6+800**

LOKASI : **STA 6+900**

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Ringan  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS III. 17	NAMA RUAS Banjarnangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 35
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit





LOKASI :           **STA           7+000**

LOKASI :           **STA           7+100**

KONDISI PERKERASAN           :       Rusak Ringan  
LEBAR PERKERASAN            :       4,5            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Rusak Ringan  
LEBAR PERKERASAN            :       4,5            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarnangu - Rakit		Firdaus & Damas	36

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit



LOKASI :           **STA           7+200**

LOKASI :           **STA           7+300**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       4,5            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       4,5            M  
TYPE PERKERASAN             :       Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarnangu - Rakit		Firdaus & Damas	37

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit





LOKASI :           **STA           7+350**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       4,5            M

TYPE PERKERASAN             :       Aspal



LOKASI :           **STA           7+400**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       4,5            M

TYPE PERKERASAN             :       Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	38

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           7+500**

KONDISI PERKERASAN           :       Sedang

LEBAR PERKERASAN            :       4,5            M

TYPE PERKERASAN             :       Beton



LOKASI :           **STA           7+600**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       4,5            M

TYPE PERKERASAN             :       Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	39

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**





LOKASI :           **STA           7+700**

LOKASI :           **STA           7+740**

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       4,5            M  
TYPE PERKERASAN             :       Beton

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       4,5            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarnegara - Rakit		Firdaus & Damas	40

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnegara - Rakit



LOKASI :           **STA           7+800**

LOKASI :           **STA           7+900**

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       4,5            M  
TYPE PERKERASAN             :       Aspal


KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       4,5            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarnegara - Rakit		Firdaus & Damas	41

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnegara - Rakit





LOKASI :           **STA           8+000**

KONDISI PERKERASAN           :       Sedang

LEBAR PERKERASAN            :       4,5           M

TYPE PERKERASAN             :       Aspal

LOKASI :           **STA           8+100**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       4,5           M

TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	42

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           8+200**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       4,5           M

TYPE PERKERASAN             :       Aspal

LOKASI :           **STA           8+300**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       4,5           M



TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		Firdaus & Damas	43

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**





LOKASI : **STA 8+400**

LOKASI : **STA 8+500**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 16	Banjarmangu - Rakit		Firdaus & Damas	44

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI : **STA 8+600**

LOKASI : **STA 8+650**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4,5 M  
TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 16	Banjarmangu - Rakit		Firdaus & Damas	45

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit





LOKASI : **STA 8+700**

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Beton



LOKASI : **STA 8+800**

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 16	Banjarnangu - Rakit		Firdaus & Damas	46

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit



LOKASI : **STA 8+900**

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Aspal



LOKASI : **STA 9+000**

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 16	Banjarnangu - Rakit		Firdaus & Damas	47

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit





LOKASI :           **STA           9+100**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       4,5            M

TYPE PERKERASAN             :       Aspal



LOKASI :           **STA           9+200**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       4,5            M

TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 16	Banjarmangu - Rakit		Firdaus & Damas	48

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           9+300**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       4,5            M

TYPE PERKERASAN             :       Aspal



LOKASI :           **STA           9+400**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       4,5            M


TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 16	Banjarmangu - Rakit		Firdaus & Damas	49

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**





LOKASI :           **STA            9+500**

LOKASI :           **STA            9+600**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    4,5            M  
 TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    4,5            M  
 TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 16	Banjarmangu - Rakit		Firdaus & Damas	50

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA            9+700**

LOKASI :           **STA            9+800**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    4,5            M  
 TYPE PERKERASAN             :    Aspal


KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    4,5            M  
 TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 16	Banjarmangu - Rakit		Firdaus & Damas	51

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**






LOKASI : **STA 9+900**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4,5 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 9+910**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4,5 M

TYPE PERKERASAN : Beton

NO. RUAS III. 16	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 52
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI : **STA 9+940**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4,5 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 10+000**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4,5 M

TYPE PERKERASAN : Aspal

NO. RUAS III. 16	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 53
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit





LOKASI : STA 10+100

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Aspal



LOKASI : STA 10+200

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 16	Banjarnangu - Rakit		Firdaus & Damas	54

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit



LOKASI : STA 10+300

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Aspal



LOKASI : STA 10+330

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 4,5 M  
 TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 16	Banjarnangu - Rakit		Firdaus & Damas	55

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit





LOKASI : **STA 10+350**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal



LOKASI : **STA 10+400**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4,5 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 16	Banjarnangu - Rakit		Firdaus & Damas	56

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit



LOKASI : **STA 10+500**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4,5 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 10+600**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 16	Banjarnangu - Rakit		Firdaus & Damas	57

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit



LOKASI : **STA 10+700**

KONDISI PERKERASAN : Sedang

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

LOKASI : **STA 10+800**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

NO. RUAS III. 16	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 58
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI : **STA 10+900**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Beton

LOKASI : **STA 10+950**

KONDISI PERKERASAN : Baik

LEBAR PERKERASAN : 4 M

TYPE PERKERASAN : Aspal

NO. RUAS III. 16	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 59
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI : STA 11+000

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

LOKASI : STA 11+100

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

NO. RUAS III. 16	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 60
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI : STA 11+200

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

LOKASI : STA 11+300

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

NO. RUAS III. 16	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 61
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI : STA 11+400

LOKASI : STA 11+500


KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 4 M  
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 4 M  
 TYPE PERKERASAN : Aspal

NO. RUAS III. 16	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 62
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI : STA 11+600

LOKASI : STA 11+700

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 4 M  
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 4 M  
 TYPE PERKERASAN : Aspal

NO. RUAS III. 16	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY Firdaus & Damas	HALAMAN 63
---------------------	----------------------------------	------------------------	-----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI : STA 11+800

LOKASI : STA 11+900


KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 16	Banjarmangu - Rakit		Firdaus & Damas	64

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI : STA 12+000

LOKASI : STA

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 4 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN :  
LEBAR PERKERASAN : M  
TYPE PERKERASAN :

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 16	Banjarmangu - Rakit		Firdaus & Damas	65

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           12+100**

LOKASI :           **STA           12+200**

KONDISI PERKERASAN :       Sedang  
LEBAR PERKERASAN       :       6            M  
TYPE PERKERASAN        :       Aspal

KONDISI PERKERASAN :       Sedang  
LEBAR PERKERASAN       :       6            M  
TYPE PERKERASAN        :       Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 1
---------------------	----------------------------------	------------------------	----------------------------------	--------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           12+300**

LOKASI :           **STA           12+400**

KONDISI PERKERASAN :       Baik  
LEBAR PERKERASAN       :       6            M  
TYPE PERKERASAN        :       Aspal

KONDISI PERKERASAN :       Baik  
LEBAR PERKERASAN       :       6            M  
TYPE PERKERASAN        :       Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 2
---------------------	----------------------------------	------------------------	----------------------------------	--------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           12+500**

LOKASI :           **STA           12+550**

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN            :     6            M  
TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN            :     6            M  
TYPE PERKERASAN             :     Beton

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 3
---------------------	----------------------------------	------------------------	----------------------------------	--------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           12+600**

LOKASI :           **STA           12+700**

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN            :     6            M  
TYPE PERKERASAN             :     Beton

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN            :     6            M  
TYPE PERKERASAN             :     Beton

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 4
---------------------	----------------------------------	------------------------	----------------------------------	--------------

## FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI :            **STA            12+800**

LOKASI :            **STA            12+900**

KONDISI PERKERASAN            :    Baik  
LEBAR PERKERASAN                :    6            M  
TYPE PERKERASAN                 :    Beton

KONDISI PERKERASAN            :    Baik  
LEBAR PERKERASAN                :    6            M  
TYPE PERKERASAN                 :    Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	5

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI :           **STA           13+000**

LOKASI :           **STA           13+100**

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN            :     6            M  
TYPE PERKERASAN             :     Beton

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN            :     6            M  
TYPE PERKERASAN             :     Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	6

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI :           **STA           13+125**

LOKASI :           **STA           13+200**

KONDISI PERKERASAN           :     Sedang  
LEBAR PERKERASAN            :     6            M  
TYPE PERKERASAN             :     Aspal

KONDISI PERKERASAN           :     Baik  
LEBAR PERKERASAN            :     6            M  
TYPE PERKERASAN             :     Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	7

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI :           **STA           13+300**

LOKASI :           **STA           13+400**


KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       6            M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       6            M  
TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	8

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI :           **STA           13+450**

LOKASI :           **STA           13+500**

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       6            M  
TYPE PERKERASAN             :       Beton

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       6            M  
TYPE PERKERASAN             :       Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	9

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI :           **STA           13+600**

LOKASI :           **STA           13+700**


KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	10

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI :           **STA           13+750**

LOKASI :           **STA           13+800**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	11

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



14/10/25 09:41:51  
7°23'42"S 109°34'33"E  
Kabupaten Banjarnegara  
#Ruas III. Banjarmangu - Rakit  
#STA 13+900  
#Survei Jalan #DPUPR Kab Banjarnegara



14/10/25 09:43:58  
7°23'42"S 109°34'30"E  
Kabupaten Banjarnegara  
#Ruas III. Banjarmangu - Rakit  
#STA 14+000  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 13+900**

LOKASI : **STA 14+000**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal


NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	12

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



14/10/25 09:45:42  
7°23'42"S 109°34'27"E  
Kabupaten Banjarnegara  
#Ruas III. Banjarmangu - Rakit  
#STA 14+100  
#Survei Jalan #DPUPR Kab Banjarnegara



14/10/25 09:48:22  
7°23'43"S 109°34'25"E  
Kabupaten Banjarnegara  
#Ruas III. Banjarmangu - Rakit  
#STA 14+170  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 14+100**

LOKASI : **STA 14+170**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	13

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI : **STA 14+200**

LOKASI : **STA 14+300**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Beton

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	14

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI : **STA 14+390**

LOKASI : **STA 14+400**

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	15

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI :           **STA           14+500**

LOKASI :           **STA           14+600**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	16

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI :           **STA           14+700**

LOKASI :           **STA           14+800**

KONDISI PERKERASAN           :    Sedang  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Rusak Ringan  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	17

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :               **STA               14+900**

KONDISI PERKERASAN               :       Rusak Ringan

LEBAR PERKERASAN               :       6               M

TYPE PERKERASAN               :       Aspal

LOKASI :               **STA               15+000**

KONDISI PERKERASAN               :       Sedang

LEBAR PERKERASAN               :       6               M

TYPE PERKERASAN               :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	MELDA & DAHLAN	18

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :               **STA               15+100**

KONDISI PERKERASAN               :       Rusak Ringan

LEBAR PERKERASAN               :       6               M

TYPE PERKERASAN               :       Aspal

LOKASI :               **STA               15+200**

KONDISI PERKERASAN               :       Rusak Ringan

LEBAR PERKERASAN               :       6               M

TYPE PERKERASAN               :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	MELDA & DAHLAN	19

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           15+300**

LOKASI :           **STA           15+400**

KONDISI PERKERASAN           :       Sedang  
LEBAR PERKERASAN            :       6                M  
TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       6                M  
TYPE PERKERASAN             :       Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 20
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           15+460**

LOKASI :           **STA           15+500**

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       6                M  
TYPE PERKERASAN             :       Beton

KONDISI PERKERASAN           :       Baik  
LEBAR PERKERASAN            :       6                M  
TYPE PERKERASAN             :       Beton

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 21
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           15+600**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    6            M

TYPE PERKERASAN             :    Beton

LOKASI :           **STA           15+700**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    6            M

TYPE PERKERASAN             :    Beton

NO. RUAS <b>III. 17</b>	NAMA RUAS <b>Banjarmangu - Rakit</b>	<b>DPUPR KAB.BANJARNEGARA</b>	PETUGAS SURVEY <b>MELDA &amp; DAHLAN</b>	HALAMAN <b>22</b>
----------------------------	-----------------------------------------	-------------------------------	---------------------------------------------	----------------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           15+800**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    6            M

TYPE PERKERASAN             :    Beton

LOKASI :           **STA           15+900**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    6            M

TYPE PERKERASAN             :    Beton

NO. RUAS <b>III. 17</b>	NAMA RUAS <b>Banjarmangu - Rakit</b>	<b>DPUPR KAB.BANJARNEGARA</b>	PETUGAS SURVEY <b>MELDA &amp; DAHLAN</b>	HALAMAN <b>23</b>
----------------------------	-----------------------------------------	-------------------------------	---------------------------------------------	----------------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           16+000**

LOKASI :           **STA           16+100**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Beton

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 24
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           16+200**

LOKASI :           **STA           16+300**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Beton

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 25
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :               **STA               16+400**

KONDISI PERKERASAN               :       Baik

LEBAR PERKERASAN               :       6               M

TYPE PERKERASAN               :       Beton



LOKASI :               **STA               16+500**

KONDISI PERKERASAN               :       Baik

LEBAR PERKERASAN               :       6               M

TYPE PERKERASAN               :       Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarnangu - Rakit		MELDA & DAHLAN	26

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarnangu - Rakit**




LOKASI :               **STA               16+600**

KONDISI PERKERASAN               :       Baik

LEBAR PERKERASAN               :       6               M

TYPE PERKERASAN               :       Beton



LOKASI :               **STA               16+700**

KONDISI PERKERASAN               :       Baik

LEBAR PERKERASAN               :       6               M

TYPE PERKERASAN               :       Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarnangu - Rakit		MELDA & DAHLAN	27

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarnangu - Rakit**





LOKASI :           **STA           16+800**

LOKASI :           **STA           16+900**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton

NO. RUAS III. 17	NAMA RUAS Banjarnangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 28
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarnangu - Rakit**



LOKASI :           **STA           17+000**

LOKASI :           **STA           17+100**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton

NO. RUAS III. 17	NAMA RUAS Banjarnangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 29
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarnangu - Rakit**





14/10/25 10:45:06  
 7°24'57"S 109°33'39"E  
 Kabupaten Banjarnegara  
 #Ruas III. Banjarnegaru - Rakit  
 #STA 17+200  
 #Survei Jalan #DPUPR Kab Banjarnegara



14/10/25 10:47:07  
 7°24'58"S 109°33'38"E  
 Kabupaten Banjarnegara  
 #Ruas III. Banjarnegaru - Rakit  
 #STA 17+260  
 #Survei Jalan #DPUPR Kab Banjarnegara

LOKASI :           **STA           17+200**

LOKASI :           **STA           17+260**

KONDISI PERKERASAN           :       Sedang  
 LEBAR PERKERASAN            :       6            M  
 TYPE PERKERASAN             :       Beton

KONDISI PERKERASAN           :       Baik  
 LEBAR PERKERASAN            :       6            M  
 TYPE PERKERASAN             :       Aspal

NO. RUAS III. 17	NAMA RUAS Banjarnegaru - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 30
---------------------	-----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarnegaru - Rakit**



14/10/25 10:48:04  
 7°24'59"S 109°33'36"E  
 Kabupaten Banjarnegara  
 #Ruas III. Banjarnegaru - Rakit  
 #STA 17+300  
 #Survei Jalan #DPUPR Kab Banjarnegara



14/10/25 10:49:28  
 7°25'0"S 109°33'34"E  
 Kabupaten Banjarnegara  
 #Ruas III. Banjarnegaru - Rakit  
 #STA 17+380  
 #Survei Jalan #DPUPR Kab Banjarnegara

LOKASI :           **STA           17+300**

LOKASI :           **STA           17+380**

KONDISI PERKERASAN           :       Rusak Ringan  
 LEBAR PERKERASAN            :       6            M  
 TYPE PERKERASAN             :       Aspal

KONDISI PERKERASAN           :       Baik  
 LEBAR PERKERASAN            :       6            M  
 TYPE PERKERASAN             :       Beton

NO. RUAS III. 17	NAMA RUAS Banjarnegaru - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 31
---------------------	-----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarnegaru - Rakit**





LOKASI :           **STA           17+400**

LOKASI :           **STA           17+500**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Beton

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 32
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           17+600**

LOKASI :           **STA           17+700**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Beton

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 33
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**





14/10/25 10:59:26  
7°25'8"S 109°33'23"E  
Kabupaten Banjarnegara  
#Ruas III. Banjarnangu - Rakit  
#STA 17+800  
#Survei Jalan #DPUPR Kab Banjarnegara



14/10/25 11:01:16  
7°25'9"S 109°33'20"E  
Kabupaten Banjarnegara  
#Ruas III. Banjarnangu - Rakit  
#STA 17+900  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : STA 17+800

LOKASI : STA 17+900

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Beton

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarnangu - Rakit		MELDA & DAHLAN	34

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit



14/10/25 11:02:35  
7°25'11"S 109°33'17"E  
Kabupaten Banjarnegara  
#Ruas III. Banjarnangu - Rakit  
#STA 18+000  
#Survei Jalan #DPUPR Kab Banjarnegara



14/10/25 11:06:46  
7°25'13"S 109°33'15"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarnangu - Rakit  
#STA 18+100  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : STA 18+000

LOKASI : STA 18+100

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Beton

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarnangu - Rakit		MELDA & DAHLAN	35

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit





LOKASI :           **STA           18+200**

LOKASI :           **STA           18+300**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton

NO. RUAS <b>III. 17</b>	NAMA RUAS <b>Banjarnegu - Rakit</b>	<b>DPUPR KAB.BANJARNEGARA</b>	PETUGAS SURVEY <b>MELDA &amp; DAHLAN</b>	HALAMAN <b>36</b>
----------------------------	----------------------------------------	-------------------------------	---------------------------------------------	----------------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarnegu - Rakit**



LOKASI :           **STA           18+400**

LOKASI :           **STA           18+500**


KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton

NO. RUAS <b>III. 17</b>	NAMA RUAS <b>Banjarnegu - Rakit</b>	<b>DPUPR KAB.BANJARNEGARA</b>	PETUGAS SURVEY <b>MELDA &amp; DAHLAN</b>	HALAMAN <b>37</b>
----------------------------	----------------------------------------	-------------------------------	---------------------------------------------	----------------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarnegu - Rakit**





LOKASI :           **STA           18+600**

LOKASI :           **STA           18+700**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 38
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           18+800**

LOKASI :           **STA           18+900**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 39
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**





LOKASI :           **STA           19+000**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    6            M

TYPE PERKERASAN             :    Beton

LOKASI :           **STA           19+100**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    6            M

TYPE PERKERASAN             :    Beton

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 40
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           19+200**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    6            M

TYPE PERKERASAN             :    Beton

LOKASI :           **STA           19+300**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    6            M

TYPE PERKERASAN             :    Beton

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 41
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**





LOKASI :           **STA           19+400**

LOKASI :           **STA           19+485**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Beton

KONDISI PERKERASAN           :    Sedang  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUKR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	42

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           19+500**

LOKASI :           **STA           19+600**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUKR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	43

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**





LOKASI :           **STA           19+630**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton



LOKASI :           **STA           19+700**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	44

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           19+800**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton



LOKASI :           **STA           19+900**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	45

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**





LOKASI :           **STA           19+970**

KONDISI PERKERASAN           :       Sedang

LEBAR PERKERASAN            :       6                M

TYPE PERKERASAN             :       Aspal

LOKASI :           **STA           20+000**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       6                M

TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarnangu - Rakit		MELDA & DAHLAN	46

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarnangu - Rakit**



LOKASI :           **STA           20+100**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       6                M

TYPE PERKERASAN             :       Aspal

LOKASI :           **STA           20+200**

KONDISI PERKERASAN           :       Baik

LEBAR PERKERASAN            :       6                M

TYPE PERKERASAN             :       Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarnangu - Rakit		MELDA & DAHLAN	47

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarnangu - Rakit**





LOKASI :           **STA           20+300**

LOKASI :           **STA           20+400**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUKR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	48

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           20+500**

LOKASI :           **STA           20+600**

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Aspal

KONDISI PERKERASAN           :    Baik  
 LEBAR PERKERASAN            :    6            M  
 TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUKR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	49

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

**RUAS JALAN : Banjarmangu - Rakit**





LOKASI :           **STA           20+700**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    6            M

TYPE PERKERASAN             :    Aspal



LOKASI :           **STA           20+800**

KONDISI PERKERASAN           :    Sedang

LEBAR PERKERASAN            :    6            M

TYPE PERKERASAN             :    Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 50
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**  
**RUAS JALAN : Banjarmangu - Rakit**



LOKASI :           **STA           20+900**

KONDISI PERKERASAN           :    Baik

LEBAR PERKERASAN            :    6            M

TYPE PERKERASAN             :    Aspal



LOKASI :           **STA           21+000**

KONDISI PERKERASAN           :    Sedang

LEBAR PERKERASAN            :    6            M

TYPE PERKERASAN             :    Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 51
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**  
**RUAS JALAN : Banjarmangu - Rakit**





Kabupaten Banjarnegara  
#Ruas III. 17 Banjarnangu - Rakit  
#STA 21+100  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : STA 21+100

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal



Kabupaten Banjarnegara  
#Ruas III. 17 Banjarnangu - Rakit  
#STA 21+155  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : STA 21+155

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarnangu - Rakit		MELDA & DAHLAN	52

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit



14/10/25 13:12:28  
7°26'7"S 109°31'50"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarnangu - Rakit  
#STA 21+200  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : STA 21+200

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Beton



14/10/25 13:14:32  
7°26'6"S 109°31'50"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarnangu - Rakit  
#STA 21+235  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : STA 21+235

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal


NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarnangu - Rakit		MELDA & DAHLAN	53

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarnangu - Rakit



14/10/25 13:16:05  
7°26'7"S 109°31'47"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarnangu - Rakit



14/10/25 13:18:36  
7°26'7"S 109°31'44"E  
Kabupaten Banjarnegara  
#Ruas III. 17 Banjarnangu - Rakit



#Ruas III. 17 Banjarmasin - Rakit  
#STA 21+300  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI :           **STA           21+300**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Aspal



#Ruas III. 17 Banjarmasin - Rakit  
#STA 21+400  
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI :           **STA           21+400**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	54

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmasin - Rakit



LOKASI :           **STA           21+500**

KONDISI PERKERASAN           :    Baik  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Beton

LOKASI :           **STA           21+555**

KONDISI PERKERASAN           :    Sedang  
LEBAR PERKERASAN            :    6            M  
TYPE PERKERASAN             :    Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	55

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmasin - Rakit



#Survei Jalan #DPUPR Kab Banjarnegara			#Survei Jalan #DPUPR Kab Banjarnegara		
LOKASI :	<b>STA</b>	<b>21+600</b>	LOKASI :	<b>STA</b>	<b>21+700</b>
KONDISI PERKERASAN	:	Sedang	KONDISI PERKERASAN	:	Baik
LEBAR PERKERASAN	:	6 M	LEBAR PERKERASAN	:	6 M
TYPE PERKERASAN	:	Aspal	TYPE PERKERASAN	:	Aspal
NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN	
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	56	



FOTO SURVEY KONDISI JALAN TAHUN 2025					
RUAS JALAN : Banjarmangu - Rakit					
 <p>14/10/25 13:31:00 7°26'12"S 109°31'33"E Kabupaten Banjarnegara #Ruas III. 17 Banjarmangu - Rakit #STA 21+800 #Survei Jalan #DPUPR Kab Banjarnegara</p>			 <p>14/10/25 13:34:19 7°26'15"S 109°31'31"E Kabupaten Banjarnegara #Ruas III. 17 Banjarmangu - Rakit #STA 21+900 #Survei Jalan #DPUPR Kab Banjarnegara</p>		
LOKASI :	<b>STA</b>	<b>21+800</b>	LOKASI :	<b>STA</b>	<b>21+900</b>
KONDISI PERKERASAN	:	Baik	KONDISI PERKERASAN	:	Baik
LEBAR PERKERASAN	:	6 M	LEBAR PERKERASAN	:	6 M
TYPE PERKERASAN	:	Aspal	TYPE PERKERASAN	:	Aspal
NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN	
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	57	

FOTO SURVEY KONDISI JALAN TAHUN 2025					
RUAS JALAN : Banjarmangu - Rakit					
 <p>14/10/25 13:37:54 7°26'18"S 109°31'30"E Kabupaten Banjarnegara #Ruas III. 17 Banjarmangu - Rakit #STA 22+000 #Survei Jalan #DPUPR Kab Banjarnegara</p>			 <p>14/10/25 13:55:49 7°26'20"S 109°31'29"E Kabupaten Banjarnegara #Ruas III. 17 Banjarmangu - Rakit #STA 22+100 #Survei Jalan #DPUPR Kab Banjarnegara</p>		

LOKASI : STA 22+000

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal

LOKASI : STA 22+100

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 58
---------------------	----------------------------------	------------------------	----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI : STA 22+200

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal

LOKASI : STA 22+300

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 59
---------------------	----------------------------------	------------------------	----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI : STA 22+400

LOKASI : STA 22+500

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 60
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI : STA 22+600

LOKASI : STA 22+700

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 61
---------------------	----------------------------------	------------------------	----------------------------------	---------------

**FOTO SURVEY KONDISI JALAN TAHUN 2025**

RUAS JALAN : Banjarmangu - Rakit



LOKASI : STA 22+800

LOKASI : STA 22+900


KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	62

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI : STA 23+000

LOKASI : STA 23+100


KONDISI PERKERASAN : Baik  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Sedang  
 LEBAR PERKERASAN : 6 M  
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
III. 17	Banjarmangu - Rakit		MELDA & DAHLAN	63

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI : STA 23+200

LOKASI : STA 23+300

KONDISI PERKERASAN : Sedang

KONDISI PERKERASAN : Baik



TYPE PERKERASAN : Aspal

TYPE PERKERASAN : Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 66
---------------------	----------------------------------	------------------------	----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI : STA 23+800

LOKASI : STA 23+900

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 67
---------------------	----------------------------------	------------------------	----------------------------------	---------------

### FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Banjarmangu - Rakit



LOKASI : STA 24+000

LOKASI : STA 24+010

KONDISI PERKERASAN : Sedang  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik  
LEBAR PERKERASAN : 6 M  
TYPE PERKERASAN : Aspal

NO. RUAS III. 17	NAMA RUAS Banjarmangu - Rakit	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY MELDA & DAHLAN	HALAMAN 68
---------------------	----------------------------------	------------------------	----------------------------------	---------------