

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 0+000**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3,5 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+100**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 1
--------------------	----------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 0+150**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 2
--------------------	----------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



20 Okt 2025 10.08.31
7°14'53"S 109°36'23"E
Kabupaten Banjarnegara
#Ruas IV. 26 Beji - Kencen
#STA 0+300
#Survei Jalan #DPUPR Kab Banjarnegara



20 Okt 2025 10.09.40
7°14'54" S 109°36'27"E
Kabupaten Banjarnegara
#Ruas IV. 26 Beji - Kencen
#STA 0+400
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 0+300**

KONDISI PERKERASAN : Sedang
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

STA 0+700

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 3
--------------------	----------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



20 Okt 2025 10.10.35
7°14'55"S 109°36'29"E
Kabupaten Banjarnegara
#Ruas IV. 26 Beji - Kencen
#STA 0+500
#Survei Jalan #DPUPR Kab Banjarnegara



20 Okt 2025 10.11.40
7°14'58" S 109°36'30"E
Kabupaten Banjarnegara
#Ruas IV. 26 Beji - Kencen
#STA 0+600
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 0+500**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 0+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 4
--------------------	----------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 0+700**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

LOKASI : **STA 0+800**

KONDISI PERKERASAN : Baik
 LEBAR PERKERASAN : 3 M
 TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
IV. 26	Beji - Kencen		FIRDAUS & DAMAS	5

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



20 Okt 2025 10.15.05
7°14'57"S 109°36'36"E
Kabupaten Banjarnegara
#Ruas IV. 26 Beji - Kencen
#STA 0+900
#Survei Jalan #DPUPR Kab Banjarnegara



20 Okt 2025 10.16.11
7°14'57"S 109°36'40"E
Kabupaten Banjarnegara
#Ruas IV. 26 Beji - Kencen
#STA 1+000
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 0+900**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+000**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 6
--------------------	----------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



20 Okt 2025 10.17.08
7°14'56"S 109°36'43"E
Kabupaten Banjarnegara
#Ruas IV. 26 Beji - Kencen
#STA 1+100
#Survei Jalan #DPUPR Kab Banjarnegara



20 Okt 2025 10.18.18
7°14'56"S 109°36'46"E
Kabupaten Banjarnegara
#Ruas IV. 26 Beji - Kencen
#STA 1+200
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 1+100**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 1+200**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 7
--------------------	----------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



20 Okt 2025 10.19.27
7°14'56"S 109°36'49"E
Kabupaten Banjarnegara
#Ruas IV. 26 Beji - Kencen
#STA 1+300
#Survei Jalan #DPUPR Kab Banjarnegara



20 Okt 2025 10.20.32
7°14'57"S 109°36'52"E
Kabupaten Banjarnegara
#Ruas IV. 26 Beji - Kencen
#STA 1+400
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 1+300**

LOKASI : **STA 1+400**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 8
--------------------	----------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



20 Okt 2025 10.21.28
7°14'56"S 109°36'56"E
Kabupaten Banjarnegara
#Ruas IV. 26 Beji - Kencen
#STA 1+500
#Survei Jalan #DPUPR Kab Banjarnegara



20 Okt 2025 10.22.32
7°14'56"S 109°36'58"E
Kabupaten Banjarnegara
#Ruas IV. 26 Beji - Kencen
#STA 1+600
#Survei Jalan #DPUPR Kab Banjarnegara

LOKASI : **STA 1+500**

LOKASI : **STA 1+600**

KONDISI PERKERASAN : Baik
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Beton

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 9
--------------------	----------------------------	------------------------	-----------------------------------	--------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 1+700**

LOKASI : **STA 1+800**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Beton

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Beton

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 10
--------------------	----------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 1+900**

LOKASI : **STA 2+000**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 11
--------------------	----------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 2+100**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+200**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 12
--------------------	----------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 2+300**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 2+400**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Beton

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 13
--------------------	----------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 2+500**

LOKASI : **STA 2+600**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Beton

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
IV. 26	Beji - Kencen		FIRDAUS & DAMAS	14

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 2+700**

LOKASI : **STA 2+800**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Beton

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
IV. 26	Beji - Kencen		FIRDAUS & DAMAS	15

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 2+900**

LOKASI : **STA 3+000**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 16
--------------------	----------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 3+100**

LOKASI : **STA 3+200**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 17
--------------------	----------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA** **3+300**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Beton

LOKASI : **STA** **3+400**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 18
--------------------	----------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA** **3+500**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Beton

LOKASI : **STA** **3+600**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Beton

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 19
--------------------	----------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 3+700**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 3+800**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
IV. 26	Beji - Kencen		FIRDAUS & DAMAS	20

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 3+900**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 4+000**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS	NAMA RUAS	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY	HALAMAN
IV. 26	Beji - Kencen		FIRDAUS & DAMAS	21

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 4+100**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 4+200**

KONDISI PERKERASAN : Rusak Ringan
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 22
--------------------	----------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 4+300**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

LOKASI : **STA 4+400**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 23
--------------------	----------------------------	------------------------	-----------------------------------	---------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 4+500**

LOKASI : **STA 4+600**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 24
---------------------------	-----------------------------------	-------------------------------	--	----------------------

FOTO SURVEY KONDISI JALAN TAHUN 2025

RUAS JALAN : Beji - Kencen



LOKASI : **STA 4+680**

LOKASI : **STA 4+687**

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

KONDISI PERKERASAN : Rusak Berat
LEBAR PERKERASAN : 3 M
TYPE PERKERASAN : Aspal

NO. RUAS IV. 26	NAMA RUAS Beji - Kencen	DPUPR KAB.BANJARNEGARA	PETUGAS SURVEY FIRDAUS & DAMAS	HALAMAN 25
---------------------------	-----------------------------------	-------------------------------	--	----------------------